



Chemistry

EI	PPM	+/-	
Cr	ND	<67	Pass
Cd	ND	<35	Pass
Hg	ND	<25	Pass
Pb	19	5	Pass

Aiming Image




Signature: _____

Date: _____


Chemistry

EI	PPM	+/-	
Cr	ND	<54	Pass
Cd	ND	<10	Pass
Hg	ND	<4	Pass
Pb	ND	<3	Pass

Aiming Image



Spectrum




Signature: _____

Date: _____


Chemistry

EI	PPM	+/-	
Cr	ND	<72	Pass
Cd	ND	<38	Pass
Hg	ND	<30	Pass
Pb	ND	<15	Pass

Aiming Image



Spectrum



Signature: _____

Date: _____